

GB Instruction for use
FI Käytöohje

POWERTEX

Aluminum Chain Block PACB-S1

User Manual




POWERTEX Chain Block PACB-S1 0,25 – 3 ton

Instruction for use (GB) (Original instructions)

Read through these user instructions carefully before using the chain block. Improper operation may lead to hazardous situations!

General safety provisions

- Only to be used by trained operator.
- Do not use in explosive or corrosive environment.
- Temperature range: -10°C up to +50°C.
- Check the function of the chain block before use. See "Daily checks" on page 3.
- Full function of the brake system can only be secured at a minimum load of 30 kg for capacities (WLL) up to 1 ton, and for capacities (WLL) above 1 ton, the minimum load to be greater than 3% of the rated capacity (WLL).
- Do not exceed the maximum load.
- Handle the chain block with care. Do not throw the block about or let it fall to the ground.
- Do not use the chain block for welding work where it is exposed to welding spatter or current.
- The chain block must not be used for lifting persons.



Data

| Model | WLL (ton) | Hand force max. (N) | Load chain (mm) | Number of falls | Hand chain (mm) | Hand chain length (m) | Weight* (kg) |
|-----------------|--------------|------------------------|--------------------|-----------------|--------------------|--------------------------|-----------------|
| PACB-S1/250 | 0,25 | 147 | 3,0 x 9 | 1 | 2,5 x 12 | 2,5 | 2,6 |
| PACB-S1/500 | 0,5 | 187 | 4,0 x 12 | 1 | 3,5 x 16 | 2,5 | 4,6 |
| PACB-S1/1000 | 1,0 | 280 | 5,6 x 15,7 | 1 | 3,5 x 16 | 2,5 | 6,6 |
| PACB-S1/2000 | 2,0 | 360 | 8,0 x 24 | 1 | 4,8 x 22 | 2,5 | 13,5 |
| PACB-S1/3000 | 3,0 | 340 | 7,1 x 20,1 | 2 | 4,8 x 22 | 2,5 | 17,0 |
| PACB-S1OLP/250 | 0,25 | 147 | 3,0 x 9 | 1 | 2,5 x 12 | 2,5 | 2,6 |
| PACB-S1OLP/500 | 0,5 | 187 | 4,0 x 12 | 1 | 3,5 x 16 | 2,5 | 4,6 |
| PACB-S1OLP/1000 | 1,0 | 280 | 5,6 x 15,7 | 1 | 3,5 x 16 | 2,5 | 6,6 |
| PACB-S1OLP/2000 | 2,0 | 360 | 8,0 x 24 | 1 | 4,8 x 22 | 2,5 | 13,5 |
| PACB-S1OLP/3000 | 3,0 | 340 | 7,1 x 20,1 | 2 | 4,8 x 22 | 2,5 | 17,0 |

* With standard 3 m lifting height. OLP = With overload protection.

Dimensions

| WLL ton | A (mm) | B (mm) | C (mm) | D (mm) | E (mm) | F (mm) | H min. (mm) |
|---------|-----------|-----------|-----------|-----------|-----------|-----------|----------------|
| 0,25 | 75 | 77 | 44 | 32 | 35,5 | 21 | 225 |
| 0,5 | 92 | 89 | 51 | 34,5 | 42 | 23 | 265 |
| 1,0 | 110 | 102 | 55 | 42,5 | 49,5 | 27 | 295 |
| 2,0 | 145 | 138 | 78,5 | 46,5 | 58,5 | 35 | 390 |
| 3,0 | 165 | 120 | 68 | 50 | 61,9 | 37 | 470 |

Safety factor: 4:1.

Dynamic test coefficient: WLL x 1,5.

Generally according to EN 13157.

Function

The load hook is raised or lowered by pulling on the hand chain.

The load will remain where it is even when the hand chain is released because of the effective reaction brake.

Max. hand force need to be respected to avoid overloading of the hoist.

The Over Load Protection (OLP) versions are additionally equipped with an overload protection device that will limit the force that can be applied using the hand chain.

If the OLP device is activated the hand chain will rotate but the hoist will not continue to lift, only lowering is possible.

The overload protection device is adjusted in the factory to approx. 1,3 x WLL and the device normally don't need to be adjusted.

Suspension of chain block

Suspend the block from an eye, shackle, girder trolley etc. with sufficient load capacity. With the chain tightened, both hooks must be vertically aligned.



NB! No bending stresses may be applied to block, hooks or load chain.

Raising/lowering

Only use straps and slings of sufficient load capacity. Check that the load is not anchored to the floor/ground or is otherwise fixed before making the lift. Ensure that the load chain hangs vertically and has no kinks. The hand chain must also be in good condition and easily accessible. The load is raised or lowered by pulling the hand chain in either direction.

Warning: Do not overload the brake by prolonged lowering. It may cause brake function to fail.

Warning:

- Only hand power from a single person is permitted on the hand chain. If the chain feels too heavy, use a bigger chain block or reduce the load.
- Make sure no-one stands beneath a hanging load.
- Do not step onto a hanging load.
- Do not raise or lower so far that the load hook hits the block housing.
- The chain block must not be used for pulling loads.
- The block must not be subjected to dynamic stresses, for example where a load connected to the block is launched from a height.
- Do not leave a block with a suspended load unattended.

Attachment of loads

Check the equipment before use. Improper attachment of loads can be highly dangerous (see Figs. 2 a – 2 e).




Fig 2 a
The sling is applying
load to the hook tip




Fig 2 b
Excessive top angle
on sling!
α max. 60°




Fig 2 c
Hook latch
obstructed




Fig 2 d
Hook tip
subject to additional
bending stress




Fig 2 e
Load chain must not
be used as a sling

Multiple lifting

Multiple lifting entails special risks. This is when two or perhaps more hoists are used simultaneously for the same load. Danger to persons and material damage can arise due to dynamic stresses and uneven load distribution causing individual hoists to become overloaded. A competent person with experience in multiple lifting must therefore supervise this type of lifting tasks.

The total weight of the target object and its load distribution must be known or calculated.

For a variety of reasons, the centre of gravity can be difficult to determine, and thus so will the distribution of the load each chain hoist must bear.

In cases where heavy, bulky loads must be handled and it is not possible to estimate all factors correctly, the working load limit (WLL) of each chain hoist must be reduced by at least 25%.

Daily checks

After every working day on which the chain block has been used, the following should be checked:

- Is the chain block deformed or otherwise damaged? Are any parts missing?
- Is any deformation or other damage visible on the suspension device (eye, shackle, bolt, trolley etc.)?
- Are the hooks intact or have any hooks opened? Are the hook latches correct and functional?
- Wipe down the chain block and oil the load chain as required.
- The load chain must be undamaged, i.e. no signs of wear and no deformed or otherwise damaged links.
- The load chain must not be kinked or twisted. With two-fall or multi-fall chain blocks there is a risk of the chain twisting if the bottom hook assembly ends up looped through the chain sling – usually during refitting or moving the chain block between work stations. See Fig 3.
- The hand chain must also be in good condition.
- The brake function must be intact.

In the event of faults or failures, the block must be repaired and carefully checked by a specialist before reuse.

Continuous maintenance - lubrication

Oil the hook latches and bearings. Grease the pawl and ratchet and also the gear. Lubrication must be sparingly and carefully applied so no grease gets on the brake disk. Oil the load chain for longer life.

Periodic checks

Periodic checks are normally carried out yearly to detect and remedy any faults. If required (e.g. high frequency of use), more frequent checks may be carried out. See "Checklist for periodic checks". Measure hooks and chain to detect any changes in shape.

Checks on load hook (see Fig. 4 and Table 1)

Opening dimension E on the hooks is important. A hook with too large a maximum dimension has been exposed to overloading or overheating. It therefore does not have the necessary load capacity. The hooks may also have been exposed to long-term wear (dimension K).

Hooks must be discarded and replaced if:

- The maximum E value is exceeded (according to Table 1)
- The minimum K value falls short (according to Table 1)
- The hook shows signs of cracking
- The hook is deformed or otherwise damaged

Defective hooks must be replaced before using the chain block again.




FIG. 3 The chain must not be twisted

Fig. 4 Load hook

Table 1 Load hook

| WLL t | 0,25 | 0,5 | 1 | 2 | 3 |
|------------------------|---------|---------|---------|---------|---------|
| Model | PACB-S1 | PACB-S1 | PACB-S1 | PACB-S1 | PACB-S1 |
| Dimension E nominal mm | 35,5 | 42 | 49,5 | 58,5 | 61,9 |
| Dimension E max mm | 40,82 | 48,3 | 56,92 | 67,27 | 71,18 |
| Dimension K nominal mm | 12,9 | 15,6 | 20,0 | 26,5 | 31,2 |
| Dimension K min mm | 11,6 | 14,0 | 18,0 | 23,8 | 28,0 |

Checks on load chain (see Fig. 5 and Table 2)

Inspect the load chain over its whole length to detect any deformed or otherwise damaged links. Make a check measurement of suspect links. Measure the worn areas Also, every 300 mm (normally), make check measurements of the internal length of 5 links (pitch dimension 5xP – according to Table 2).




Fig 5 Checking load chain dimensions

Table 2 Load chain

| Max. load t | 0,25 | 0,5 | 1 | 2 | 3 |
|----------------------------------|---------|---------|---------|---------|---------|
| Model | PACB-S1 | PACB-S1 | PACB-S1 | PACB-S1 | PACB-S1 |
| Link diameter nominal mm | 3,0 | 4,0 | 5,6 | 8,0 | 7,1 |
| Link diameter min. mm | 2,7 | 3,6 | 5,04 | 7,2 | 6,39 |
| Pitch dimension (5xP) nominal mm | 45,0 | 60,0 | 78,5 | 120 | 100,5 |
| Pitch dimension (5xP) max. mm | 46,35 | 61,8 | 80,86 | 123,6 | 103,52 |

The load chain must be discarded and replaced if:

- cracks are detected on any link
- any link is deformed or otherwise damaged
- The minimum value of any link's diameter falls short
- the maximum value of the pitch dimension is exceeded at any point
- the chain is damaged by overheating or has been affected by weld splatter

Load chains must **not** be repaired – they must be replaced by new chain. If it is desired to lengthen the chain, it must be replaced by a new and longer chain.

Replacement of the chain shall be performed professionally by an authorized repairer and the chain must meet the requirements stated in the standard EN 818-7, Grade T from the following manufacturers: Chaineries Limousines, Pewag, Kito Chain, Retezarna or Rud.

Repairs

The chain block must not be modified. Repairs must be carried out by specialists. Damaged parts must only be replaced with original Powertex spare parts. Order them through your dealer.

Declaration of conformity

SCM Citra OY
Asessorinkatu 3-7
20780 Kaarina
Finland
www.powertex-products.com

hereby declares that the POWERTEX product as described above is in compliance with EC Machinery Directive 2006/42/EC & EN 13157.

Checklist for periodic checks (normally yearly – more frequently if necessary)

| Daily | Yearly | Inspection items | Inspection method | Note |
|-------------------|--------|---|---------------------------------------|--|
| Labels | | | | |
| X | X | Rating plate | Visual | If the plate is hard to read - replace it |
| Function | | | | |
| X | X | Raising and lowering function | Test without load | A low snapping noise should be audible |
| - | X | Raising and lowering function | Test with rated weight for min 300 mm | Load chain sprocket and chain work well together. Brake works. Hand pulling on the hand chain feels even and not too heavy |
| Hooks | | | | |
| X | -X | Hook opening | Visual Measurements | Looks normal See Fig. 4 and Table 1 |
| X | X | Deformation | Visual | No visible deformation |
| X | X | Hook bearing | Visual | No abnormal play |
| X | -X | Wear, cracks, deformation and corrosion | Visual Measurements | No visible damage See Fig. 4 and Table 1 |
| X | X | Hook latches | Visual | Works, spring undamaged |
| Load chain | | | | |
| X | -X | Pitch | Visual Measurement | Looks normal. Measure in case of doubt See Fig. 5 and Table 2 |
| X | -X | Wear | Visual Measurement | Looks problem-free. Measure in case of doubt See Fig. 5 and Table 2 |
| X | X | Deformation | Visual | No deformation. Measure in case of doubt |
| X | X | Cracks etc. | Visual | No cracks |
| X | X | Rust | Visual | No rust |
| Housing | | | | |
| X | X | Frame | Visual | No deformation and no rust |
| X | X | Gearbox | Visual | No deformation |
| - | X | Gears | Visual after dismantling | No serious wear or fractures |
| - | X | Load chain sprocket | Visual after dismantling | No serious wear or cracks. No fractures or deformation |
| - | X | Hand chain sprocket | Visual | No serious wear or cracks. No fractures or deformation |
| - | X | Bearings | Visual, testing | No damage, smooth running |
| Screws | | | | |
| X | X | Screws, nuts, rivets, cotters etc. | Visual | Must not be missing. Tighten loose items. Replace as necessary |
| Brake | | | | |
| - | X | Brake disk | Visual | Replace if worn |
| - | X | Brake screw | Visual | No serious wear |
| - | X | Pawl and ratchet | Visual | Replace worn parts. Carefully lubricate with grease |


POWERTEX-nostopylypyrä PACB-S1 0,25 – 3 tonnia

Käyttöohje (FI)

Lue tämä käyttöohje ennen kuin otat käsiketjutaljan käyttöön. Virheellinen käyttö voi aiheuttaa vaaroja!

Yleiset turvaohjeet

- Käytetään vain koulutetun henkilön toimesta
- Älä käytä räjähdyssvaarallisessa tai syövyttävässä ympäristössä
- Käyttölämpötila: -10°C - +50°C.
- Tarkista talja ennen käyttöä ja kokeile, että se toimii. Ks: "Päävittäistarkastus", sivu 7.
- Älä kuormita maksimikuormitusta enempää!
- Jarrutusjärjestelmän voidaan taata toimivan täydellä teholla vasta, kun minimikuormaa on 30 kg nimelliskuorman (WLL) ollessa yksi (1) tonni tai vähemmän. Kun nimelliskuorma (WLL) ylittää yhden (1) tonnin, minimikuorman tulisi olla yli 3% nimelliskuormasta (WLL).
- Käsittele taljaa varovasti. Älä heittele sitä äläkä raahaa sitä pitkin maata.
- Älä käytä taljaa hitsaustöissä, jotta se ei altistuisi hitsausroiskeille eikä sähkövirralle.
- Taljaa ei saa käyttää ihmisten nostamiseen.



Tekniset tiedot

| Malli | WLL (ton) | Käyttövoima max (N) | Nostokettinki (mm) | Ketjuluku | Käsiketju (mm) | Käsiketjun pituus (m) | Paino* (kg) |
|-----------------|--------------|------------------------|-----------------------|-----------|-------------------|--------------------------|----------------|
| PACB-S1/250 | 0,25 | 147 | 3,0 x 9 | 1 | 2,5 x 12 | 2,5 | 2,6 |
| PACB-S1/500 | 0,5 | 187 | 4,0 x 12 | 1 | 3,5 x 16 | 2,5 | 4,6 |
| PACB-S1/1000 | 1,0 | 280 | 5,6 x 15,7 | 1 | 3,5 x 16 | 2,5 | 6,6 |
| PACB-S1/2000 | 2,0 | 360 | 8,0 x 24 | 1 | 4,8 x 22 | 2,5 | 13,5 |
| PACB-S1/3000 | 3,0 | 340 | 7,1 x 20,1 | 2 | 4,8 x 22 | 2,5 | 17,0 |
| PACB-S1OLP/250 | 0,25 | 147 | 3,0 x 9 | 1 | 2,5 x 12 | 2,5 | 2,6 |
| PACB-S1OLP/500 | 0,5 | 187 | 4,0 x 12 | 1 | 3,5 x 16 | 2,5 | 4,6 |
| PACB-S1OLP/1000 | 1,0 | 280 | 5,6 x 15,7 | 1 | 3,5 x 16 | 2,5 | 6,6 |
| PACB-S1OLP/2000 | 2,0 | 360 | 8,0 x 24 | 1 | 4,8 x 22 | 2,5 | 13,5 |
| PACB-S1OLP/3000 | 3,0 | 340 | 7,1 x 20,1 | 2 | 4,8 x 22 | 2,5 | 17,0 |

*Nostokorkeus standardi 3 m. OLP = Ylikuormitussuojalla.

Mitat

| WLL ton | A (mm) | B (mm) | C (mm) | D (mm) | E (mm) | F (mm) | H min. (mm) |
|---------|-----------|-----------|-----------|-----------|-----------|-----------|----------------|
| 0,25 | 75 | 77 | 44 | 32 | 35,5 | 21 | 225 |
| 0,5 | 92 | 89 | 51 | 34,5 | 42 | 23 | 265 |
| 1,0 | 110 | 102 | 55 | 42,5 | 49,5 | 27 | 295 |
| 2,0 | 145 | 138 | 78,5 | 46,5 | 58,5 | 35 | 390 |
| 3,0 | 165 | 120 | 68 | 50 | 61,9 | 37 | 470 |

Varmuuskerroin: 4:1.

Dynaaminen testikerroin: WLL x 1,5.

Yleisesti EN 13157 mukaan.

Toiminta

Koukkua nostetaan ja lasketaan käsiketjua vetämällä. Tehokas jarru pitää kuorman paikallaan, kun käsiketjusta päästetään irti. Ylikuormitukseen välittämiseksi enimmäiskäyttövoimaa ei pidä ylittää.

Jos taljaan on asennettu ylikuormitussuoja, se rajoittaa taljaan kohdistuvaa voimaa käsiketjusta vedettäessä.

Ylikuormitussuojan aktivoituessa käsiketjua voi pyörittää, mutta taakkaa ei voi nostaa, sen voi vain laskea.

Ylikuormitussuoja säädetään tehtaalla kuormalle n. 1,3 x WLL ja sitä ei tavallisesti tarvitse sen jälkeen enää säätää.

Taljan ripustaminen

Varmista, että talja ripustetaan riittävän kantokykyiseen silmukkaan, sakkeliin, palkissa olevaan siirtovaunuun ym. Kun ketju on kiristetty, koukkujen on oltava pystysuorassa linjassa keskenään.



HUOM! Taljaa ja koukuja on varjeltava sellaisilta rasituksilta, jotka aiheuttavat vääräntymistä..

Nosto/lasku

Käytä vain riittävän kantavia nostoapuvälineitä. Varmista, että kuormaa ei ole ankkuroitu lattiaan/maan eikä se ole muutenkaan juuttunut, kun nosto alkaa. Varmista, että kuormaketju riippuu pystysuorassa eikä ole sykkyrällä. Käsiketjun on oltava myös hyvässä järjestysessä ja siihen on päästävä helposti käsiksi. Kuormaa nostetaan ja lasketaan vetämällä käsiketjua jompaankumpaan suuntaan.

Varoitus: Älä ylikuormita jarrua pitkittämällä kuorman laskua. Se voi vahingoittaa jarrua.

Varoitus:

- Käsiketjun saa kohdistaa vain yhden miehen käsiin! Jos tuntuu liian raskaalta, vähennä kuormaa tai valitse suurempi talja!
- Varmista, että kukaan ei ole päässyt koukkuun!
- Älä seisoo riippuvan kuorman päällä!
- Älä nostaa tai laske liian pitkälle, jottei koukku osuu taljaan!
- Käsiketjutalja ei saa käyttää kuormien vetämiseen.
- Taljaa ei saa altistaa dynaamiselle rasitukselle esimerkiksi siten, että taljaan kytketty kuorma tiputetaan korkealta!
- Älä koskaan jätä riippuvaa kuormaa taljaan vartioimatta!

Kuorman kiinnitys

Tarkista laitteisto ennen käyttöä. Virheet kuorman kiinnityksessä voivat aiheuttaa vakavia vaaroja (ks. kuvia 2 a – 2 e).



Fig 2 a

Silmukka kuormittaa koukun kärkeä!




Fig 2 b

Yläkulma liian suuri silmukassa!
α enint. 60°




Fig 2 c

Koukun lukko estetty!




Fig 2 d

Koukun kärkeen vaikuttaa lisäksi väärästi kosketusrasitus!




Fig 2 e

Kuormaketju ei saa käyttää silmikkana!

Nostaminen usealla nostolaitteella

Usealla nostolaitteella nostamiseen liittyy erityisiä riskejä. Kuorman nostamiseen käytetään tällöin samanaikaisesti kahta tai useampaa taljaa. Dynaaminen rasitus ja epätasainen kuorman jakautuminen voivat aiheuttaa yksittäisten taljojen ylikuormittumisen, jolloin seurauksena voi olla henkilöihin kohdistuvia vaaroja ja aineellisia vahinkoja. Siksi tämän typipisä nostotöitä tulee olla valvomassa pätevän henkilön, jolla on kokemusta usealla nostolaitteella nostamisesta.

Nostettavan kohteen kokonaispaino ja kuormitukseen jakautuminen tulee olla tiedossa tai nämä tiedot tulee laskea.

Monista eri syistä massakeskipiste ja sitten myös kunkin taljan kannattelemien kuormitukseen jakautuminen voi olla vaikeaa määrittää. Jos käsittelijänä on raskaita, suuria kuormia, eläkä kaikkia tekijöitä ole mahdollista arvioida oikein, kunkin taljan enimmäisyökumma (WLL) tulee pienentää vähintään 25%:lla.

Päivittäistarkastus

Joka päivä ennen taljan käyttöä on otettava huomioon seuraavat asiat:

- Onko talja vääräntynyt tai muuten vahingoittunut? Puuttuuko yksi tai useampia osia?
- Näkyykö vääräntymisen tai muun vaurioitumisen merkkejä ripustusvälineistössä (silmukka, sakkeli, pultti tms.)?
- Ovatko koukut kunnossa tai onko jokin niistä vääräntynyt?
- Ovatko koukkujen salvat kunnossa ja toimintakykyisiä?
- Pyyhi talja kuivaksi ja öljyä ketju tarvittaessa.
- Kuorma- ja käsiketjun on oltava vahingoittumattomia, ts. se ei saa olla kulunut, eikä siinä saa olla vääräntyneitä tai muuten vahingoittuneita lenkkejä.
- Kuormaketju ei saa olla kiertynyt. Kaksi- tai useampiosaisessa taljassa on riski, että ketju kiertyy jos alatalja käännyy ketjun silmukassa väärin pään - useimmiten asennettaessa taljaa uudelleen tai siirrettäessä sitä työpisteestä toiseen. Ks. kuva 3.
- Jarrujen pitää olla kunnossa.

Jos taljassa on vikoja tai puutteita, se on tarkastettava huolella ja annettava tarvittaessa asiantuntijan korjattavaksi ennen kuin se otetaan uudelleen käyttöön.

Jatkuva ylläpito - voitelu

Öljyä koukkujen salvat ja leikarit. Lukituskoukku ja -pyörä sekä vaihteisto voidellaan rasvalla. Voideltaessa on oltava varovainen jotta voiteluainetta ei päädy jarrulevylle. Ketjun öljyäminen pidentää sen käyttöikää.

Säännöllinen tarkastus

Säännöllinen tarkastus tehdään normaalista vuosittain, jotta mahdolliset puutteet löydetään ja korjataan. Tarvittaessa (esim. usein käytettäessä) tehdään tarkastuksia useammin. Katso "Säännöllisen tarkastuksen kohdelista". Koukuja ja ketjua täytyy tarkkailla mahdollisten muodonmuutosten löytämiseksi.


Koukun tarkastus (ks. kuva 4 ja taulukko 1)

Koukkujen avautuma E on tärkeä. Jos kouku on liian avoin, se on ollut alittiina ylikuormituksesta tai kuumuudelle. Siksi sen kantokyky on riittämätön. Koukut ovat voineet myös joutua alittiaksi pitkääikaiselle kulumiselle (mitta K).

Kouku on poistettava käytöstä ja vaihdettava uuteen jos:

- E-mitan maksimiarvo ylitetään (taulukon 1 mukaan)
- K-mitan minimiarvo alitetaan (taulukon 1 mukaan)
- koukussa on halkeama tai se on väännytynyt tai muuten vahingoittunut.

Viallinen kouku on vaihdettava ennen kuin käsketjutaljaa taas käytetään!



Kuva 3 Ketju ei saa olla kiertynyt


Kuva 4. Kuormakouku

Taulukko 1 Koukun mitat

| Maksimikuorma ton | 0,25 | 0,5 | 1 | 2 | 3 |
|-------------------------|---------|---------|---------|---------|---------|
| Mallille | PACB-S1 | PACB-S1 | PACB-S1 | PACB-S1 | PACB-S1 |
| Mitta C nimellisesti mm | 35,5 | 42 | 49,5 | 58,5 | 61,9 |
| Mitta C enintään mm | 40,82 | 48,3 | 56,92 | 67,27 | 71,18 |
| Mitta K nimellisesti mm | 12,9 | 15,6 | 20,0 | 26,5 | 31,2 |
| Mitta K vähintään mm | 11,6 | 14,0 | 18,0 | 23,8 | 28,0 |

Ketjun mittaus (ks. kuva 5 ja taulukko 2)

Tarkista ketju koko pituudeltaan mahdollisten väännytysten tai muuten vahingoittuneiden lenkkien löytämiseksi. Mittaa epäilyttävä lenkit kulutuskohdista. Mittaa myös 300 mm:n välein (normaalitapauksissa) viiden lenkin sisäinen pituus (jakautumismitta 5xP taulukon 2 mukaan).



Kuva 5 Kuormaketjun mittaus

Taulukko 2 Kuormaketjun mitat

| Maksimikuorma ton | 0,25 | 0,5 | 1 | 2 | 3 |
|---|---------|---------|---------|---------|---------|
| Mallille | PACB-S1 | PACB-S1 | PACB-S1 | PACB-S1 | PACB-S1 |
| Lenkin halkaisija nimellisesti mm | 3,0 | 4,0 | 5,6 | 8,0 | 7,1 |
| Lenkin halkaisija vähintään mm | 2,7 | 3,6 | 5,04 | 7,2 | 6,39 |
| Jakautumismitta (5 x P) nimellisesti mm | 45,0 | 60,0 | 78,5 | 120 | 100,5 |
| Jakautumismitta (5 x P) enintään mm | 46,35 | 61,8 | 80,86 | 123,6 | 103,52 |

Kuormaketju on poistettava käytöstä ja vaihdettava uuteen, jos:

- jossain lenkissä havaitaan halkeama
- jokin lenkki on väännytynyt tai muuten vahingoittunut
- jokin lenkki alittaa halkaisijan minimiarvon
- jakautumismitan maksimiarvo ylittyy jossain kohtaa.
- ketju on vahingoittunut kuumuuden tai hitsausroiskeiden vaikutuksesta.

Kuormaketju ei saa korjata – se on vaihdettava uuteen alkuperäiseen ketjuun. Jos ketjua halutaan pidentää, se on vaihdettava kokonaan uuteen pidempään ketjuun.

Ketjun vaihdon voi suorittaa valtuutettu huolto ja ketjun on täytettävä standardi EN 818-7, luokka T seuraavien valmistajien: Chaineries Limousines, Pewag, Kito Chain, Retezarna tai Rud.

Korjaukset

Taljaan ei saa tehdä muutostöitä. Korjaukset on jätettävä asiantuntijan tehtäväksi. Vaihda vahingoittuneet osat ainoastaan Hakliftin alkuperäisiin osiin.

Vaatimustenmukaisuusvakuutus

SCM Citra OY
Asessorinkatu 3-7
20780 Kaarina
Finland
www.powertex-products.com

vakuuttaa, että edellä kuvatut POWERTEX-tuotteet noudattavat Euroopan parlamentin ja neuvoston direktiiviä 2006/42/EY ja EN 13157-standardia.

Säännöllisen tarkastuksen kohdelista (normaalisti vuosittain – tarvittaessa useammin)


| Päivittäin | Vuosittain | Tarkastuskohteet | Tarkastustapa | Huom. |
|--------------------|------------|---|---|--|
| Merkintä | | | | |
| X | X | Typpikilpi | Silmämäärisesti | Jos kilpi on vaikealukuinen, vaihda |
| Toiminta | | | | |
| X | X | Nosto- ja laskutoiminto | Kokeile ilman kuormaa | Pehmeästi napsahtavan äänen tulee kuulua |
| - | X | Nosto- ja laskutoiminto | Kokeile nimelliskuormalla vähintään 300 mm matka. | Akselipyörä ja ketju toimivat hyvin yhdessä. Jarru toimii. Ohjausketjun vaatima käsitöövoma on tasainen eikä liian suuri |
| Koukut | | | | |
| X | -X | Koukun avonaisuus | Silmämäärisesti Mittaa | Näyttää normaalilta Ks. kuvaa 4 ja taulukko 1 |
| X | X | Vääntyneisyys | Silmämäärisesti | Ei näkyvää vääntyneisyyttä |
| X | X | Koukun laakerointi | Silmämäärisesti | Ei epänormaalialla klappia |
| X | -X | Slitage, revner, deformation og korrosion | Silmämäärisesti Mål | Ei näkyviä vaurioita Ks. kuvaa 4 ja taulukko 1 |
| X | X | Koukun salvat | Silmämäärisesti, kokeile | Toimii, jouset vahingoittumattomia |
| Kuormaketju | | | | |
| X | -X | Jakautuminen | Silmämäärisesti Mittaa | Näyttää normaalilta. Mittaa jos epäilyttää Ks. kuvaa 5 ja taulukko 2 |
| X | -X | Kuluminen | Silmämäärisesti Mittaa | Näyttää virheettömältä. Mittaa jos epäilyttää Ks. kuvaa 5 ja taulukko 2 |
| X | X | Vääntyneisyys | Silmämäärisesti | Ei väännytynyt. Mittaa jos epäilyttää |
| X | X | Halkeamat | Silmämäärisesti | Ei halkeamia |
| X | X | Ruoste | Silmämäärisesti | Ei ruostetta |
| Kotelo | | | | |
| X | X | Kehys | Silmämäärisesti | Ei vääntyneisyyttä eikä ruostetta |
| X | X | Vaihdelaatikko | Silmämäärisesti | Ei vääntyneisyyttä eikä ruostetta |
| - | X | Vaihteisto | Silmämäärisesti purk. jälkeen | Ei vakavaa kuluneisuutta eikä murtumia |
| - | X | Akselipyörä | Silmämäärisesti purk. jälkeen | Ei vakavaa kuluneisuutta eikä halkeamia. Ei murtumia eikä vääntyneisyyttä |
| - | X | Ohjausketjun pyörä | Silmämäärisesti | Ei vakavaa kuluneisuutta eikä halkeamia. Ei murtumia eikä vääntyneisyyttä |
| - | X | Laakeroinnit | Silmämäärisesti, kokeile | Ei vaurioita, toimii kevyesti |
| Ruuvit | | | | |
| X | X | Ruuvit, mutterit, niitit, tapit ym | Silmämäärisesti | Mitään ei saa puuttua. Löystyneet kiristetään. Vaihda tarvittaessa |
| Jarru | | | | |
| - | X | Jarrulevy | Silmämäärisesti | Vaihda kulunut jarrulevy |
| - | X | Jarruruuvi | Silmämäärisesti | Ei vakavaa kulumista |
| - | X | Lukituskoukku ja -pyörä | Silmämäärisesti | Vaihda kulunet osat. Voitele varovasti rasvalla |

POWERTEX Chain Block PACB-S1 – Spare parts 0,25 - 3 t

When ordering spare parts, specify model, WLL, part number and the quantity needed.

When ordering chain, also specify lifting height.

If the load chain has been damaged or worn out the load sheave probably has to be replaced.



Spare parts list

| Pos | Description | Qty. | 250 kg | 500 kg | 1000 kg | 2000 kg | 3000kg |
|-----|--|------|---------------------|---------------------|---------------------|---------------------|---------------------|
| 1 | Warning tag | 1 | 16.10PACBS10250-1 | 16.10PACBS10500-1 | 16.10PACBS11000-1 | 16.10PACBS12000-1 | 16.10PACBS13000-1 |
| 2 | Screw and washer | 4 | 16.10PACBS10250-2 | 16.10PACBS10500-2 | 16.10PACBS11000-2 | 16.10PACBS12000-2 | 16.10PACBS13000-2 |
| 3 | Hand wheel cover | 1 | 16.10PACBS10250-3 | 16.10PACBS10500-3 | 16.10PACBS11000-3 | 16.10PACBS12000-3 | 16.10PACBS13000-3 |
| 4 | Lock nut | 1 | 16.10PACBS10250-4 | 16.10PACBS10500-4 | 16.10PACBS11000-4 | 16.10PACBS12000-4 | 16.10PACBS13000-4 |
| 5 | Washer | 1 | 16.10PACBS10250-5 | 16.10PACBS10500-5 | 16.10PACBS11000-5 | 16.10PACBS12000-5 | 16.10PACBS13000-5 |
| 6 | Hand chain | 1 | 16.10PACBS10250-6 | 16.10PACBS10500-6 | 16.10PACBS11000-6 | 16.10PACBS12000-6 | 16.10PACBS13000-6 |
| 7 | Master link | 1 | 16.10PACBS10250-7 | 16.10PACBS10500-7 | 16.10PACBS11000-7 | 16.10PACBS12000-7 | 16.10PACBS13000-7 |
| 8 | Hand wheel | 1 | 16.10PACBS10250-8 | 16.10PACBS10500-8 | 16.10PACBS11000-8 | 16.10PACBS12000-8 | 16.10PACBS13000-8 |
| 8L | Hand wheel with over-load limiter assembly | 1 | 16.10PACBS10250-8L | 16.10PACBS10500-8L | 16.10PACBS11000-8L | 16.10PACBS12000-8L | 16.10PACBS13000-8L |
| 8-1 | Lock nut | 1 | 16.10PACBS10250-8-1 | 16.10PACBS10500-8-1 | 16.10PACBS11000-8-1 | 16.10PACBS12000-8-1 | 16.10PACBS13000-8-1 |
| 8-2 | Disc spring stopper | 1 | 16.10PACBS10250-8-2 | 16.10PACBS10500-8-2 | 16.10PACBS11000-8-2 | 16.10PACBS12000-8-2 | 16.10PACBS13000-8-2 |
| 8-3 | Disc spring | 1 | 16.10PACBS10250-8-3 | 16.10PACBS10500-8-3 | 16.10PACBS11000-8-3 | 16.10PACBS12000-8-3 | 16.10PACBS13000-8-3 |
| 8-4 | Disc spring plate | 1 | 16.10PACBS10250-8-4 | 16.10PACBS10500-8-4 | 16.10PACBS11000-8-4 | 16.10PACBS12000-8-4 | 16.10PACBS13000-8-4 |
| 8-5 | Brake disc | 2 | 16.10PACBS10250-8-5 | 16.10PACBS10500-8-5 | 16.10PACBS11000-8-5 | 16.10PACBS12000-8-5 | 16.10PACBS13000-8-5 |
| 8-6 | Hand wheel with overload | 1 | 16.10PACBS10250-8-6 | 16.10PACBS10500-8-6 | 16.10PACBS11000-8-6 | 16.10PACBS12000-8-6 | 16.10PACBS13000-8-6 |
| 8-7 | Overload limiter knob | 1 | 16.10PACBS10250-8-7 | 16.10PACBS10500-8-7 | 16.10PACBS11000-8-7 | 16.10PACBS12000-8-7 | 16.10PACBS13000-8-7 |
| 9 | Ratchet disc | 1 | 16.10PACBS10250-9 | 16.10PACBS10500-9 | 16.10PACBS11000-9 | 16.10PACBS12000-9 | 16.10PACBS13000-9 |
| 10 | Brake disc | 2 | 16.10PACBS10250-10 | 16.10PACBS10500-10 | 16.10PACBS11000-10 | 16.10PACBS12000-10 | 16.10PACBS13000-10 |
| 11 | Brake hub | 1 | 16.10PACBS10250-11 | 16.10PACBS10500-11 | 16.10PACBS11000-11 | 16.10PACBS12000-11 | 16.10PACBS13000-11 |
| 12 | Retainer ring | 2 | 16.10PACBS10250-12 | 16.10PACBS10500-12 | 16.10PACBS11000-12 | 16.10PACBS12000-12 | 16.10PACBS13000-12 |
| 13 | Pawl | 2 | 16.10PACBS10250-13 | 16.10PACBS10500-13 | 16.10PACBS11000-13 | 16.10PACBS12000-13 | 16.10PACBS13000-13 |
| 14 | Pawl spring | 2 | 16.10PACBS10250-14 | 16.10PACBS10500-14 | 16.10PACBS11000-14 | 16.10PACBS12000-14 | 16.10PACBS13000-14 |
| 15 | Stay bolt | 4 | 16.10PACBS10250-15 | 16.10PACBS10500-15 | 16.10PACBS11000-15 | 16.10PACBS12000-15 | 16.10PACBS13000-15 |
| 16 | Side plate A assembly | 1 | 16.10PACBS10250-16 | 16.10PACBS10500-16 | 16.10PACBS11000-16 | 16.10PACBS12000-16 | 16.10PACBS13000-16 |
| 17 | Load chain guide A | 1 | 16.10PACBS10250-17 | 16.10PACBS10500-17 | 16.10PACBS11000-17 | 16.10PACBS12000-17 | 16.10PACBS13000-17 |
| 18 | Load sheave | 1 | 16.10PACBS10250-18 | 16.10PACBS10500-18 | 16.10PACBS11000-18 | 16.10PACBS12000-18 | 16.10PACBS13000-18 |
| 19 | Load chain | 1 | 16.10PACBS10250-19 | 16.10PACBS10500-19 | 16.10PACBS11000-19 | 16.10PACBS12000-19 | 16.10PACBS13000-19 |
| 20 | Anchor hanger | 1 | 16.10PACBS10250-20 | 16.10PACBS10500-20 | 16.10PACBS11000-20 | 16.10PACBS12000-20 | 16.10PACBS13000-20 |
| 21 | Anchor pin | 1 | 16.10PACBS10250-21 | 16.10PACBS10500-21 | 16.10PACBS11000-21 | 16.10PACBS12000-21 | 16.10PACBS13000-21 |
| 22 | Load chain guide B | 1 | 16.10PACBS10250-22 | 16.10PACBS10500-22 | 16.10PACBS11000-22 | 16.10PACBS12000-22 | 16.10PACBS13000-22 |
| 23 | Stay bolt sleeve | 4 | 16.10PACBS10250-23 | 16.10PACBS10500-23 | 16.10PACBS11000-23 | 16.10PACBS12000-23 | 16.10PACBS13000-23 |
| 24 | Side plate B | 1 | 16.10PACBS10250-24 | 16.10PACBS10500-24 | 16.10PACBS11000-24 | 16.10PACBS12000-24 | 16.10PACBS13000-24 |
| 25 | Top pin | 1 | 16.10PACBS10250-25 | 16.10PACBS10500-25 | 16.10PACBS11000-25 | 16.10PACBS12000-25 | 16.10PACBS13000-25 |
| 26 | Pinion shaft | 1 | 16.10PACBS10250-26 | 16.10PACBS10500-26 | 16.10PACBS11000-26 | 16.10PACBS12000-26 | 16.10PACBS13000-26 |
| 27 | Load gear | 1 | 16.10PACBS10250-27 | 16.10PACBS10500-27 | 16.10PACBS11000-27 | 16.10PACBS12000-27 | 16.10PACBS13000-27 |
| 28 | Disc gear | 2 | 16.10PACBS10250-28 | 16.10PACBS10500-28 | 16.10PACBS11000-28 | 16.10PACBS12000-28 | 16.10PACBS13000-28 |
| 29 | Reinforced plate | 1 | 16.10PACBS10250-29 | 16.10PACBS10500-29 | 16.10PACBS11000-29 | 16.10PACBS12000-29 | 16.10PACBS13000-29 |
| 30 | Gear case | 1 | 16.10PACBS10250-30 | 16.10PACBS10500-30 | 16.10PACBS11000-30 | 16.10PACBS12000-30 | 16.10PACBS13000-30 |
| 31 | Nameplate | 1 | 16.10PACBS10250-31 | 16.10PACBS10500-31 | 16.10PACBS11000-31 | 16.10PACBS12000-31 | 16.10PACBS13000-31 |
| 32 | Rivet | 4 | 16.10PACBS10250-32 | 16.10PACBS10500-32 | 16.10PACBS11000-32 | 16.10PACBS12000-32 | 16.10PACBS13000-32 |
| 33 | Top hook assembly | 1 | 16.10PACBS10250-33 | 16.10PACBS10500-33 | 16.10PACBS11000-33 | 16.10PACBS12000-33 | 16.10PACBS13000-33 |
| 34 | Latch kit | 2 | 16.10PACBS10250-34 | 16.10PACBS10500-34 | 16.10PACBS11000-34 | 16.10PACBS12000-34 | 16.10PACBS13000-34 |
| 35 | Bottom hook assembly | 1 | 16.10PACBS10250-35 | 16.10PACBS10500-35 | 16.10PACBS11000-35 | 16.10PACBS12000-35 | 16.10PACBS13000-35 |
| 36 | Load pin and nut | 1 | 16.10PACBS10250-36 | 16.10PACBS10500-36 | 16.10PACBS11000-36 | 16.10PACBS12000-36 | 16.10PACBS13000-36 |
| 37 | Bottom hook holder | 2 | 16.10PACBS10250-37 | 16.10PACBS10500-37 | 16.10PACBS11000-37 | 16.10PACBS12000-37 | 16.10PACBS13000-37 |
| 38 | Idle sheave | 1 | 16.10PACBS10250-38 | 16.10PACBS10500-38 | 16.10PACBS11000-38 | 16.10PACBS12000-38 | 16.10PACBS13000-38 |
| 39 | Quill roller | 22 | 16.10PACBS10250-39 | 16.10PACBS10500-39 | 16.10PACBS11000-39 | 16.10PACBS12000-39 | 16.10PACBS13000-39 |
| 40 | Idle shaft | 1 | 16.10PACBS10250-40 | 16.10PACBS10500-40 | 16.10PACBS11000-40 | 16.10PACBS12000-40 | 16.10PACBS13000-40 |
| 41 | Screw and nut | 2 | 16.10PACBS10250-41 | 16.10PACBS10500-41 | 16.10PACBS11000-41 | 16.10PACBS12000-41 | 16.10PACBS13000-41 |
| 42 | Screw and nut | 1 | 16.10PACBS10250-42 | 16.10PACBS10500-42 | 16.10PACBS11000-42 | 16.10PACBS12000-42 | 16.10PACBS13000-42 |
| 43 | Washer | 2 | 16.10PACBS10250-43 | 16.10PACBS10500-43 | 16.10PACBS11000-43 | 16.10PACBS12000-43 | 16.10PACBS13000-43 |

Product compliance and conformity

SCM Citra OY
Asessorinkatu 3-7



20780 Kaarina
Finland
www.powertex-products.com

CertMax+

The CertMax+ system is a unique leading edge certification management system which is ideal for managing a single asset or large equipment portfolio across multiple sites. Designed by the Lifting Solutions Group, to deliver optimum asset integrity, quality assurance and traceability, the system also improves safety and risk management levels.



Marking

The POWERTEX Chain Block is equipped with a RFID (Radio-Frequency Identification) tag, which is a small electronic device, that consist of a small chip and an antenna. It provides a unique identifier for the block.



The POWERTEX Chain Block is **CE** marked

Standard: EN 13157

Warning tag

The warning tag shows some specific and important situations, in which you must pay special attention, when using POWERTEX Chain Blocks and Lever Hoists.




User Manuals

You can always find the valid and updated User Manuals on the web. The manual is updated continuously and valid only in the latest version.

NB! The English version is the Original instruction.

The manual is available as a download under the following link:
www.powertex-products.com/manuals



POWERTEX



www.powertex-products.com